


# PRZEKROJE POPRZECZNE


SKALA 1:100

0 + 096




$P_{wyk} = 0,00 \text{ m}^2$   
 $P_{nas} = 3,08 \text{ m}^2$   
 $L_{hum} = 7,00 \text{ m}$

0 + 116




$P_{wyk} = 0,47 \text{ m}^2$   
 $P_{nas} = 0,43 \text{ m}^2$   
 $L_{hum} = 7,16 \text{ m}$

0 + 136




$P_{wyk} = 0,96 \text{ m}^2$   
 $P_{nas} = 0,12 \text{ m}^2$   
 $L_{hum} = 7,00 \text{ m}$

0 + 149




$P_{wyk} = 9,12 \text{ m}^2$   
 $P_{nas} = 0,00 \text{ m}^2$   
 $L_{hum} = 9,10 \text{ m}$

0 + 161



$P_{wyk} = 0,20 \text{ m}^2$   
 $P_{nas} = 2,53 \text{ m}^2$   
 $L_{hum} = 8,16 \text{ m}$

0 + 184



$P_{wyk} = 0,68 \text{ m}^2$   
 $P_{nas} = 0,00 \text{ m}^2$   
 $L_{hum} = 7,10 \text{ m}$